



www.OdometerGears.com

Volvo 850 Horn Repair Kit Installation

If your horn sounds on its own the probable cause is defective horn contacts in the steering wheel, this kit repairs this concern.

It is always best to disconnect the battery before working with an air bag!

Volvo 850 Horn Fix FAQ

All horn kits are manufactured by Odometer Gears Ltd.

Step 1



Unscrew both bolt using torx driver

Step 2



Slide top contact towards the top and twist to remove

Step 3



Use cutters to remove the old horn contact. Leave the ring connector attached.

Step 4



Use your finger and press the new bushing up into the hole

Step 5

Step 6



Use an adjustable pliers to squeeze the bushing all the way



Insert the bolt with washer in from the top

Step 7



Insert the connector into the "J" nut

Step 8



Screw bolt into contact assembly and tighten snug. Don't over tighten.

Additional notes to remove R and R the steering wheel

Required tools:
T-30, 27 torx driver
Cutters
Pliers

Remove fuse #34 -- horn/windshield wiper

This is important to not reinstall the fuse until the airbag is reconnected. Causing the airbag light to come on and will have to take the vehicle to the dealer to reset the light at your cost.

Turn wheel all the way to one side. There is a hole on the back of the wheel.

Inside is a T-30 Torx screw that should be removed. Turn the wheel all the way to the other side and remove the other screw.

When reconnecting the airbag steering wheel assembly to the steering wheel, tighten the right (looking at the steering wheel while seated in the driver's seat) torx first. This effects horn operation.



www.OdometerGears.com